

12695335
01/10/2018 12:09 PM \$18.00
Book - 10637 Pg - 4077
ADAM BARDINER
RECORDER, SALT LAKE COUNTY, UTAH
GREAT BASIN ENGINEERING
5746 S 1475 E
SOUTH OGDEN UT 84403
BY: SNA, DEPUTY - MI 1 P.

CORRECTION AFFIDAVIT
Summit Vista Subdivision
Taylorsville City, Salt Lake County, Utah


I, Andy Hubbard, Professional Land Surveyor, and also the Surveyor who prepared the Summit Vista Subdivision Plat that by inadvertence the following information within said Subdivision plat, as filed in the official records of the Salt Lake County Recorder's Office (Entry #12627730 in Book 2017p, Page 263, has the following incorrect information:

Address for Lot 2:

It reads: 6020 South Summit Vista Boulevard

It should read: **6050 South Summit Vista Boulevard**

Signed this 14th day of December 2017



STATE OF UTAH
COUNTY OF WEBER

On the 14th day of December 2017, personally appeared before me Andy Hubbard, the signer of the instrument, who acknowledged to me that he executed the same.

Laure Hall

Notary Public
Residing at Roy, Utah
My Commission Expires:

11/26/2019

