





Unofficial Copy




Minor crack height of wall

Unofficial Copy









JUN 13 2006




Minor crack in floor

JUN 13 2006










BK1797 PG1574


Unofficial Copy




Minor crack- joint to wall

JUN 13 2008





JUN 13 2006



BK1797 PG1577